



# ZHUHAI APPRO OFFICE SUPPLIES CO., LTD

Appro (H. K) Office Supplies Co., Ltd

Add: Rm. 5520-5521 #5, NO. 32 Nanwan North Rd., Xiangzhou District 519000, Zhuhai Ch













Tel: +86-756-8634958

Fax: +86-756-8638619

email: approsales@163.com




Part No.	Type	Color	Volume	Region	For Use In	Photo
<b>Ricoh</b>						
MP C2550 BK	Toner Chip	●	10K	WW	MP C2030/2050/2530/2550; Lanier LD520C/LD525C; Savin C9020 /C9025	
MP C2550 C	Toner Chip	●	5.5K	WW	MP C2030/2050/2530/2550; Lanier LD520C/LD525C; Savin C9020 /C9025 MP C2551/2051/Lanier LD620C/LD625C/Savin C9120 /C9125	
MP C2550 M	Toner Chip	●	5.5K	WW		
MP C2550 Y	Toner Chip	●	5.5K	WW		
MP C2551 BK	Toner Chip	●	10K	WW	MP C2551/2051/Lanier LD620C/LD625C/Savin C9120 /C9125	
MP C2500 BK	Toner Chip	●	20K	WW	MP C2000/2500/3000; Gestetner DSC520/525/530; Lanier LD420C/425C/430C; Savin C2020/2525/3030	
MP C2500 C	Toner Chip	●	15K	WW		
MP C2500 M	Toner Chip	●	15K	WW		
MP C2500 Y	Toner Chip	●	15K	WW		
MP C2800 BK	Toner Chip	●	20K	WW	MP C2800/3300; Lanier LD533C	
MP C2800 C	Toner Chip	●	15K	WW	MP C2800/3300; Lanier LD533C; MP C3001/3501/Gestetner MPC3001 /3501/Lanier LD630C 635C/Savin C9130/9135C	
MP C2800 M	Toner Chip	●	15K	WW		
MP C2800 Y	Toner Chip	●	15K	WW		
MP C3501 BK	Toner Chip	●	22.5K	WW	MP C3001/3501/Gestetner MPC3001 /3501/Lanier LD630C 635C/Savin C9130/9135C	
MP C3500 BK	Toner Chip	●	23K	WW	MP C3500/4500; Gestetner DSC535/545; Lanier LD435C/445C; Savin C3535/4540	
MP C3500 C	Toner Chip	●	17K	WW		
MP C3500 M	Toner Chip	●	17K	WW		
MP C3500 Y	Toner Chip	●	17K	WW		
MP C4000 BK	Toner Chip	●	23K	WW	MP C4000/5000; Lanier LD540C/550C; Savin C4040/5050	
MP C4000 C	Toner Chip	●	17K	WW	MP C4000/5000; Lanier LD540C/550C; Savin C4040/5050; MP C4501/5001/Lanier LD645C /655C/Savin C9145/C9155	
MP C4000 M	Toner Chip	●	17K	WW		
MP C4000 Y	Toner Chip	●	17K	WW		

MP C4501	Toner Chip	●	25.5K	WW	MP C4501/5001/Lanier LD645C /655C/Savin C9145/C9155	 
SP C810/C811BK	Toner Chip	●	20K	WW	Ricoh SP C810/811DN;Gestetner c7640;Lanier LP440;Savin CLP240	
SP C810/C811 C	Toner Chip	●	15K	WW		
SP C810/C811 M	Toner Chip	●	15K	WW		
SP C810/C811 Y	Toner Chip	●	15K	WW		
SP C820/C821BK	Toner Chip	●	20K	WW	Ricoh SP C820/821DN;Lanier LP 540/550;Savin CLP 340/350	
SP C820/C821 C	Toner Chip	●	15K	WW		
SP C820/C821 M	Toner Chip	●	15K	WW		
SP C820/C821 Y	Toner Chip	●	15K	WW		
SP C830/C831BK	Toner Chip	●	23.5K	WW	Ricoh SP C830/C831(UNDER DEVELOPMENT)	
SP C830/C831 C	Toner Chip	●	27K	WW		
SP C830/C831 M	Toner Chip	●	27K	WW		
SP C830/C831 Y	Toner Chip	●	27K	WW		
SP C430/C431BK	Toner Chip	●	15K	WW	Ricoh SP C430/431DN;Lanier LP137/142;Savin CLP 37/42	
SP C430/C431 C	Toner Chip	●	15K	WW		
SP C430/C431 M	Toner Chip	●	15K	WW		
SP C430/C431 Y	Toner Chip	●	15K	WW		
SP C220/C222 BK	Toner Chip	●	2k	WW	Ricoh SP C220/C222	
SP C220/C222 C	Toner Chip	●	2k	WW		
SP C220/C222 M	Toner Chip	●	2k	WW		
SP C220/C222 Y	Toner Chip	●	2k	WW		
CL C4000 BK	Toner Chip	●	15K	WW	Ricoh CL4000/SP C410/C411/420	
CL C4000 C	Toner Chip	●	5K	WW		
CL C4000 M	Toner Chip	●	5K	WW		
CL C4000 Y	Toner Chip	●	5K	WW		
CL C8000 BK	Toner Chip	●		WW	Ricoh CL8000	
CL C8000 C	Toner Chip	●		WW		
CL C8000 M	Toner Chip	●		WW		
CL C8000 Y	Toner Chip	●		WW		
CL C7000 BK	Toner Chip	●	20K	WW	Ricoh AP 3800/3850,CL7000/7100;Gestetner C7435,DSC 38;Lanier 2138,LP138/235;Savin CLP28/35,SLP 28/38(Under Testing)	
CL C7000 C	Toner Chip	●	10K	WW		
CL C7000 M	Toner Chip	●	10K	WW		
CL C7000 Y	Toner Chip	●	10K	WW		
CL C7200 BK	Toner Chip	●	24K	WW	Ricoh CL7200/7300;Gestetner C7528/7535;Lanier LP 332/335;Savin CLP 128/135(Under Testing)	
CL C7200 C	Toner Chip	●	10K	WW		
CL C7200 M	Toner Chip	●	10K	WW		
CL C7200 Y	Toner Chip	●	10K	WW		
SP C231 BK	Toner Chip	●	7.2K	WW	Ricoh SP C231/232/242/311/312/320;Lanier SP C231/232/242/320;Savin SP C231/232/242/320	
SP C231 C	Toner Chip	●	6.6K	WW		
SP C231 M	Toner Chip	●	6.6K	WW		
SP C231 Y	Toner Chip	●	6.6K	WW		

Aficio 3224C BK	Toner Chip	●	25K	WW	Ricoh Aficio 3224C/3232C;Gestetner DSC 424/432;Lanier LD124/132;Savin C2410/3210	
Aficio 3224C C	Toner Chip	●	17K	WW		
Aficio 3224C M	Toner Chip	●	17K	WW		
Aficio 3224C Y	Toner Chip	●	17K	WW		
Aficio 3245C BK	Toner Chip	●	24K	WW	Ricoh Aficio 3228C/3235C/3245C; Gestetner DSC 428/435/445;Lanier LD 328/335/345;Savin C2824/3528/4535	
Aficio 3245C C	Toner Chip	●	10K	WW		
Aficio 3245C M	Toner Chip	●	10K	WW		
Aficio 3245C Y	Toner Chip	●	10K	WW		
Aficio 1224C BK	Toner Chip	●	25K	WW	Ricoh Aficio 1224/1232;Gestetner DSC 224/232;Lanier LD024/032;Savin C2408/3210(Under Testing)	
Aficio 1224C C	Toner Chip	●	17K	WW		
Aficio 1224C M	Toner Chip	●	17K	WW		
Aficio 1224C Y	Toner Chip	●	17K	WW		
Aficio 2228C BK	Toner Chip	●	19K	WW	Ricoh Aficio 2228/2232/2238;Gestetner DSC 328/332/338;Lanier LD 228/232/238;Savin C2228/2820/3224/3828	
Aficio 2228C C	Toner Chip	●	10K	WW		
Aficio 2228C M	Toner Chip	●	10K	WW		
Aficio 2228C Y	Toner Chip	●	10K	WW		
Aficio 3260C BK	Toner Chip	●	36K	WW	Ricoh Aficio 3260/color 5560;Gestetner DSC 460;Lanier LC155/160;Savin C6045/SDC555(Under Testing)	
Aficio 3260C C	Toner Chip	●	18K	WW		
Aficio 3260C M	Toner Chip	●	18K	WW		
Aficio 3260C Y	Toner Chip	●	18K	WW		
SP 5200	Toner Chip	●	25K	WW	Aficio SP 5200/5210;Lanier sp 5200/5210;Savin sp 5200/5210	
SP 3400	Toner Chip	●	5K	WW	Ricoh SP 3400/3410/3500/3510;Lanier SP 3400/3410/3500/3510;Savin SP3400/3410/3500/3510	
Type 85B	Toner Chip	●	12K	WW	NX85S/NX86S/NX96e/SP4010/SP4000	
Type 120	Toner Chip	●	15K	WW	Ricoh SP 4100N/4110N/4210N/4310N;Gestetner P7031N/7035N;Lanier LP131N/136N/37N,SP 4310N;Savin MLP31/36/37 SP 4310N	
SP 5100	Toner Chip	●	20K	WW	Ricoh SP5100;Gestetner SP5100N;Lanier SP 5100N;Savin SP5100N(Under Testing)	
SP 1000	Toner Chip	●	4K	WW	Ricoh SP 1000S/FAX 1140L/FAX 1180L/Nashuatec F111;Gestetner F111;Lanier AC116/LF225;Savin SF 3815,Savin SP1000	
SP 1100	Toner Chip	●	4K	WW	Ricoh SP 1100	

SP150	Toner Chip	●	4K	WW	Ricoh SP150	
AP600	Toner Chip	●	20K	WW	Ricoh Aficio AP2600/2610/600/610;Gestetner P7026/7126/7132/7535;Lanier AP2610,LP032/135;Savin MLP26/32/35,SLP26	
AP400	Toner Chip	●	15K	WW	Ricoh Aficio AP400/410;Gestetner P7525/7527;Lanier LP026/128;Savin MLP 25/28	
SP 4100	Toner Chip	●	15K	WW	Ricoh Aficio SP4100/4110/4210/4310;Gestetner P7031N/7035;Lanier LP131N/136N/37N/SP4310;Savin MLP 31/36/37N;Sharp SP4310N	
SP 6330	Toner Chip	●	20K	WW	Ricoh Aficio SP 6330;Lanier LP235N;Savin MLP235N (Under Testing)	
MP C300 BK	Toner Chip	●	10K	WW	Ricoh MP C300/400;Lanier LD130/140;Savin C230/240	
MP C300 C	Toner Chip	●	10K	WW		
MP C300 M	Toner Chip	●	10K	WW		
MP C300 Y	Toner Chip	●	10K	WW		
MP C3502 BK	Toner Chip	●	28K	WW	Ricoh Aficio MP C3002/3502;Lanier MP C3002/3502;Savin MP C3002/3502(UNDER DEVELOPMENT)	
MP C3502 C	Toner Chip	●	18K	WW		
MP C3502 M	Toner Chip	●	18K	WW		
MP C3502 Y	Toner Chip	●	18K	WW		
MP C4502 BK	Toner Chip	●	31K	WW	Ricoh Aficio MP C4502/5502;Lanier MP C4502/5502;Savin MP C4502/5502(UNDER DEVELOPMENT)	
MP C4502 C	Toner Chip	●	22.5K	WW		
MP C4502 M	Toner Chip	●	22.5K	WW		
MP C4502 Y	Toner Chip	●	22.5K	WW		
MP C6000 BK	Toner Chip	●	43.2K	WW	Ricoh MP C6000/7500;Lanier LD260/275;Savin C6055/7570(Under Testing)	
MP C6000 C	Toner Chip	●	21.6K	WW		
MP C6000 M	Toner Chip	●	21.6K	WW		
MP C6000 Y	Toner Chip	●	21.6K	WW		
MP C6501 BK	Toner Chip	●	43.2K	WW	Ricoh MP C6501/7501;Lanier LD365/375;Savin C9065/9075(Under Testing)	
MP C6501 C	Toner Chip	●	21.6K	WW		
MP C6501 M	Toner Chip	●	21.6K	WW		
MP C6501 Y	Toner Chip	●	21.6K	WW		
ISC2020 BK	Toner Chip	●	20K	WW	INVOTEC ISC2020	
ISC2020 C	Toner Chip	●	15K	WW		



ISC2020 M	Toner Chip	●	15K	WW		
ISC2020 Y	Toner Chip	●	15K	WW		
MP C305 BK	Toner Chip	●	12K	WW	Ricoh Aficio MPC305SP; Lanier MP C305; Savin MP C305 (UNDER DEVELOPMENT)	
MP C305 C	Toner Chip	●	4K	WW		
MP C305 M	Toner Chip	●	4K	WW		
MP C305 Y	Toner Chip	●	4K	WW		
MP C7500 BK	Toner Chip	●	20K	WW		
MP C7500 C	Toner Chip	●	10K	WW	Ricoh Aficio MP C6000/7500	
MP C7500 M	Toner Chip	●	10K	WW		
MP C7500 Y	Toner Chip	●	10K	WW		
MP C7000 BK	Toner Chip	●		WW		
MP C7000 C	Toner Chip	●		WW	Ricoh Aficio MP C7100 (Under Testing)	
MP C7000 M	Toner Chip	●		WW		
MP C7000 Y	Toner Chip	●		WW		